

qicharts2: Quality Improvement Charts for R

Jacob Anhøj¹

¹ Rigshospitalet, University of Copenhagen, Denmark

DOI: [10.21105/joss.00699](https://doi.org/10.21105/joss.00699)

Software

- [Review](#) ↗
- [Repository](#) ↗
- [Archive](#) ↗

Submitted: 19 April 2018

Published: 17 May 2018

Licence

Authors of papers retain copyright and release the work under a Creative Commons Attribution 4.0 International License ([CC-BY](#)).

Summary

`qicharts2` is an R package for making statistical process control (SPC) charts for continuous quality improvement.

SPC charts are point-and-line graphs showing a measure over time and employing statistical tests for identification of non-random variation, e.g. quality improvement or degradation. Central to SPC is the understanding of process variation over time.

The purpose of analysing process data is to know when a change occurs so that we can take appropriate action. However, numbers may change even if the process stays the same (and vice versa). So how do we distinguish changes in numbers that represent change of the underlying process from those that are essentially noise?

[Walther A. Shewhart](#), who founded SPC, described two types of variation, *common cause variation* and *special cause variation*:

Common cause variation

- is also called natural/random variation or noise,
- is present in all processes,
- is caused by phenomena that are always present within the system,
- makes the process predictable within limits.

Special cause variation

- is also called non-random variation or signal,
- is present in some processes,
- is caused by phenomena that are not normally present in the system,
- makes the process unpredictable.

The overall purpose of SPC charts is to tell the two types of variation apart.

Special cause variation in the form of minor to moderate persistent shifts in data over time is identified by the Anhoej rules for unusually long runs and unusually few crossings (Anhøj and Olesen 2014; Anhøj 2015).

Special cause variation in the form of larger, possibly transient, shifts is identified by Shewhart's 3-sigma rule (Mohammed, Worthington, and Woodall 2009) as coloured data points outside the control limits.

The control chart shown in Figure 1 displays common cause variation. This means that the process is stable and predictable, and that in the future – if nothing changes – we should expect on average 19 infections per month, and that as few as 6 and as many as 32 would be within the expected range.

The main function of `qicharts2`, `qic()`, has a simple interface with only one mandatory argument (the numbers to plot). Many more optional arguments allow for customisation of the plot, including selection of control chart type, one and two dimensional faceting, and splitting of charts into pre and post intervention periods.




Figure 1: Figure 1: Control chart of hospital infections showing random variation

With `qicharts2` comes a vignette, *Get started* (Jacob Anhøj 2018), that explains the theory behind SPC and typical uses of `qic()`.

References

- Anhøj, Jacob. 2015. “Diagnostic Value of Run Chart Analysis: Using Likelihood Ratios to Compare Run Chart Rules on Simulated Data Series.” *PLoS ONE*. <https://doi.org/10.1371/journal.pone.0121349>.
- Anhøj, Jacob, and Anne Vingaard Olesen. 2014. “Run Charts Revisited: A Simulation Study of Run Chart Rules for Detection of Non-Random Variation in Health Care Processes.” *PLoS ONE*. <https://doi.org/10.1371/journal.pone.01113825>.
- Jacob Anhøj. 2018. “Get Started with Qicharts2: A Vignette.” <https://anhoej.github.io/qicharts2/articles/qicharts2.html>.
- Mohammed, M A, P Worthington, and W H Woodall. 2009. “Plotting Basic Control Charts: Tutorial Notes for Healthcare Practitioners.” *BMJ Qual Saf* 17:137–45. <https://doi.org/10.1136/qshc.2004.012047>.